```
RCS file: /s6/cvsroot/euterpe/BOM, v
Working file: BOM
head: 5.105
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 1940; selected revisions: 4
description:
top level BOM
revision 3.942
date: 1995/08/02 06:40:58; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
Oops typo caused dout0[7] to be short to dout1[7]
revision 3.941
date: 1995/07/31 18:50:01; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
Oops drive clk54m ABD0P700V not clk54m ABD0P700V when the LVS netlist
_____
revision 3.940
date: 1995/07/30 02:47:38; author: tbr; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
Makefile.vo: change twinvia step
Makefile.tst: remove kludge from final-report
uu/uu control.pim: Latest placement. Note this was already in top level.
i h euterpe wrap.tb: Change to single configuration file
____
revision 3.939
date: 1995/07/29 23:46:20; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
When wrapping the LVS netlist don't expect the vdde pin to be at the interface
of euterpe - it's a global
_____
RCS file: /s6/cvsroot/euterpe/verify/status,v
Working file: verify/status
head: 3.64
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 64; selected revisions: 8
description:
_____
revision 3.48
date: 1995/08/02 18:49:00; author: dit00; state: Exp; lines: +21 -8
```

Exhibit D68 Page 1 of 9

```
Update
revision 3.47
date: 1995/08/01 22:56:18; author: dit00; state: Exp; lines: +1 -0
Update
_____
revision 3.46
date: 1995/08/01 17:21:20; author: lisar; state: Exp; lines: +16 -0
periodic update
_____
revision 3.45
date: 1995/07/31 22:43:12; author: dit00; state: Exp; lines: +10 -0
_____
revision 3.44
date: 1995/07/31 16:57:35; author: dit00; state: Exp; lines: +2 -0
Periodic update
_____
revision 3.43
date: 1995/07/31 16:16:56; author: lisar; state: Exp; lines: +338 -0
periodic update
-----
revision 3.42
date: 1995/07/30 20:42:10; author: dit00; state: Exp; lines: +18 -0
Perodic update
_____
revision 3.41
date: 1995/07/29 20:05:38; author: dit00; state: Exp; lines: +54 -0
Periodic update
_____
RCS file: /s6/cvsroot/euterpe/verify/random/status,v
Working file: verify/random/status
head: 2.26
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 26; selected revisions: 2
description:
revision 2.21
date: 1995/08/01 22:57:21; author: dit00; state: Exp; lines: +6 -0
Update
revision 2.20
date: 1995/07/29 20:29:47; author: dit00; state: Exp; lines: +2 -0
Periodic update
______
RCS file: /s6/cvsroot/euterpe/verify/random/template,v
Working file: verify/random/template
head: 2.33
branch:
locks: strict
access list:
keyword substitution: kv
```

Exhibit D68 Page 2 of 9

```
total revisions: 33; selected revisions: 3
description:
revision 2.26
date: 1995/08/02 18:50:53; author: dit00; state: Exp; lines: +14 -14
Update
_____
revision 2.25
date: 1995/08/01 22:57:23; author: dit00; state: Exp; lines: +147 -141
-----
revision 2.24
date: 1995/07/29 20:29:45; author: dit00; state: Exp; lines: +16 -13
Periodic update
_____
RCS file: /s6/cvsroot/euterpe/verify/toplevel/eu debug lvs.srl,v
Working file: verify/toplevel/eu debug lvs.srl
head: 41.1
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 1; selected revisions: 1
description:
_____
revision 41.1
date: 1995/07/31 18:47:44; author: lisar; state: Exp;
For the lvs netlist
RCS file: /s6/cvsroot/euterpe/verify/toplevel/hermtotest.S,v
Working file: verify/toplevel/hermtotest.S
head: 39.5
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 5; selected revisions: 2
description:
revision 39.5
date: 1995/08/01 18:37:40; author: jeffm; state: Exp; lines: +2 -2
Test did an extra machine check.
revision 39.4
date: 1995/07/31 17:32:24; author: jeffm; state: Exp; lines: +2 -2
Fixed pass3 to avoid nb antiuse preventing 2nd hermes op from going out - thus
causing a watchdog timeout with only one outstanding hermes request, instead
of two.
______
RCS file: /s6/cvsroot/euterpe/verify/toplevel/likedriverlog lvs.srl,v
Working file: verify/toplevel/likedriverlog lvs.srl
head: 41.1
branch:
locks: strict
```

Exhibit D68 Page 3 of 9

```
access list:
keyword substitution: kv
total revisions: 1; selected revisions: 1
description:
revision 41.1
date: 1995/07/31 18:47:42; author: lisar; state: Exp;
For the lvs netlist
______
RCS file: /s6/cvsroot/euterpe/verify/toplevel/nbleak debug.sig,v
Working file: verify/toplevel/nbleak debug.sig
head: 41.2
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 2; selected revisions: 1
description:
-----
revision 41.1
date: 1995/08/03 23:36:27; author: jeffm; state: Exp;
Debug signals to be used to look for cause of nb shrinkage.
_____
RCS file: /s6/cvsroot/euterpe/verify/toplevel/rawdata debug.srl,v
Working file: verify/toplevel/rawdata debug.srl
head: 41.5
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 5; selected revisions: 4
description:
_____
revision 41.5
date: 1995/08/02 18:47:23; author: dit00; state: Exp; lines: +6 -6
Fixed some trace names
______
revision 41.4
date: 1995/08/01 23:18:48; author: jeffm; state: Exp; lines: +9 -0
Added signals to trace hermes clocks.
revision 41.3
date: 1995/07/31 22:34:36; author: jeffm; state: Exp; lines: +2 -2
Fixed a coupla signal names.
revision 41.2
date: 1995/07/31 22:04:36; author: jeffm; state: Exp; lines: +60 -18
Added more signals.
______
RCS file: /s6/cvsroot/euterpe/verify/toplevel/template,v
Working file: verify/toplevel/template
head: 1.148
branch:
locks: strict
```

Exhibit D68 Page 4 of 9

```
access list:
keyword substitution: kv
total revisions: 148; selected revisions: 8
description:
revision 1.136
date: 1995/08/02 18:48:26; author: dit00; state: Exp; lines: +2 -2
Update
revision 1.135
date: 1995/07/31 23:02:30; author: lisar; state: Exp; lines: +157 -157
Add l
revision 1.134
date: 1995/07/31 22:42:34; author: dit00; state: Exp; lines: +2 -2
More time for dram load config1
_____
revision 1.133
date: 1995/07/31 22:36:16; author: lisar; state: Exp; lines: +43 -43
Add lvs list
revision 1.132
date: 1995/07/31 17:06:06; author: dit00; state: Exp; lines: +4 -4
Update
_____
revision 1.131
date: 1995/07/30 20:42:37; author: dit00; state: Exp; lines: +3 -3
Perodic update
_____
revision 1.130
date: 1995/07/30 00:15:58; author: lisar; state: Exp; lines: +33 -33
Add l simulator
revision 1.129
date: 1995/07/29 20:28:57; author: dit00; state: Exp; lines: +5 -7
Periodic update
RCS file: /s6/cvsroot/euterpe/verilog/BOM, v
Working file: verilog/BOM
head: 6.9
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 1390; selected revisions: 4
description:
top level verilog BOM
revision 4.16
date: 1995/08/02 06:40:40; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
Oops typo caused dout0[7] to be short to dout1[7]
revision 4.15
```

Exhibit D68 Page 5 of 9

```
date: 1995/07/31 18:49:44; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
Oops drive clk54m_ABD0P700V not clk54m ABD0P700V when the LVS netlist
revision 4.14
date: 1995/07/30 02:47:21; author: tbr; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
Makefile.vo: change twinvia step
Makefile.tst: remove kludge from final-report
uu/uu control.pim: Latest placement. Note this was already in top level.
i_h_euterpe_wrap.tb: Change to single configuration file
revision 4.13
date: 1995/07/29 23:45:56; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
When wrapping the LVS netlist don't expect the vdde pin to be at the interface
of euterpe - it's a global
______
RCS file: /s6/cvsroot/euterpe/verilog/bsrc/BOM,v
Working file: verilog/bsrc/BOM
head: 346.6
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 1737; selected revisions: 5
description:
_____
revision 339.2
date: 1995/08/02 06:40:21; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
Oops typo caused dout0[7] to be short to dout1[7]
revision 339.1
date: 1995/07/31 18:49:25; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
     euterpe wrap.V
Oops drive clk54m ABD0P700V not clk54m ABD0P700V when the LVS netlist
revision 339.0
date: 1995/07/30 02:46:54; author: tbr; state: Exp; lines: +1 -1
Release Target: euterpe/verilog/bsrc
Makefile.vo: change twinvia step
Makefile.tst: remove kludge from final-report
uu/uu control.pim: Latest placement. Note this was already in top level.
```

Exhibit D68 Page 6 of 9

```
i_h_euterpe_wrap.tb: Change to single configuration file
revision 338.2
date: 1995/07/30 02:46:41; author: tbr; state: Exp; lines: +5 -5
releasebom: File needs to be up-to-date to use commit -r
revision 338.1
date: 1995/07/29 23:45:32; author: lisar; state: Exp; lines: +2 -2
Release Target: euterpe/verilog/bsrc
    euterpe wrap.V
When wrapping the LVS netlist don't expect the vdde pin to be at the interface
of euterpe - it's a global
______
RCS file: /s6/cvsroot/euterpe/verilog/bsrc/Makefile.tst,v
Working file: verilog/bsrc/Makefile.tst
head: 40.104
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 104; selected revisions: 2
description:
_____
revision 40.101
date: 1995/08/02 06:57:10; author: tbr; state: Exp; lines: +8 -8
make .csyn instead of .splvs to make sure we always run a check
_____
revision 40.100
date: 1995/07/30 02:38:03; author: tbr; state: Exp; lines: +8 -9
remove kludge in final-report
_____
RCS file: /s6/cvsroot/euterpe/verilog/bsrc/Makefile.vo,v
Working file: verilog/bsrc/Makefile.vo
head: 27.45
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 45; selected revisions: 1
description:
revision 27.43
date: 1995/07/30 02:26:38; author: tbr; state: Exp; lines: +2 -2
remove -v1h and -v2h from twinvia per wampler
______
RCS file: /s6/cvsroot/euterpe/verilog/bsrc/euterpe.status,v
Working file: verilog/bsrc/euterpe.status
head: 24.83
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 83; selected revisions: 1
```

Exhibit D68 Page 7 of 9

```
description:
revision 24.77
date: 1995/08/01 02:08:23; author: mws; state: Exp; lines: +27 -5
Add note of bug that SAAS treats its src=dst register as a pair
 for source dependency analysis even though it is architecturally single octlt.
 Add note of possible tricky perf improvement to skip BHicMid and get directly
 to BFetch on sequentially entered ICache lines that miss.
 Expand on note of CC being busy longer on ICache misses to guarantee
 forward progress.
______
RCS file: /s6/cvsroot/euterpe/verilog/bsrc/euterpe wrap.V,v
Working file: verilog/bsrc/euterpe wrap.V
head: 15.104
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 104; selected revisions: 3
description:
-----
revision 15.100
date: 1995/08/02 06:40:00; author: lisar; state: Exp; lines: +2 -2
Oops typo caused dout0[7] to be short to dout1[7]
_____
revision 15.99
date: 1995/07/31 18:49:04; author: lisar; state: Exp; lines: +6 -1
Oops drive clk54m ABD0P700V not clk54m ABD0P700V when the LVS netlist
_____
revision 15.98
date: 1995/07/29 23:44:50; author: lisar; state: Exp; lines: +2 -4
When wrapping the LVS netlist don't expect the vdde pint to be at the interface
of euterpe - it's a global
______
RCS file: /s6/cvsroot/euterpe/verilog/bsrc/uu/BOM,v
Working file: verilog/bsrc/uu/BOM
head: 218.1
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 480; selected revisions: 2
description:
revision 215.0
date: 1995/07/30 02:45:48; author: tbr; state: Exp; lines: +1 -1
Release Target: euterpe/verilog/bsrc
Makefile.vo: change twinvia step
Makefile.tst: remove kludge from final-report
uu/uu control.pim: Latest placement. Note this was already in top level.
i h euterpe wrap.tb: Change to single configuration file
____
revision 214.1
```

Exhibit D68 Page 8 of 9

```
date: 1995/07/30 02:45:39; author: tbr; state: Exp; lines: +2 -2
releasebom: File needs to be up-to-date to use commit -r
RCS file: /s6/cvsroot/euterpe/verilog/lvs/Makefile,v
Working file: verilog/lvs/Makefile
head: 1.8
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 8; selected revisions: 2
description:
revision 1.8
date: 1995/07/31 18:51:30; author: lisar; state: Exp; lines: +2 -4
Add missing dependancy
_____
revision 1.7
date: 1995/07/31 00:47:38; author: lisar; state: Exp; lines: +63 -19
Emerged the behavioral cache and tag into an edif2 (form the splvs) then
successfully build a non-working mif.mm! Note used xplus5.1
RCS file: /s6/cvsroot/euterpe/verilog/lvs/l euterpe wrap.parm,v
Working file: verilog/lvs/l euterpe wrap.parm
head: 1.2
branch:
locks: strict
access list:
keyword substitution: kv
total revisions: 2; selected revisions: 1
description:
revision 1.2
date: 1995/07/30 00:05:59; author: lisar; state: Exp; lines: +27 -27
Append an X to the name of the cache and tag arrays.
______
```

Exhibit D68 Page 9 of 9